

Date:

2025/8/24

Report Type:

*Maintenance***Customer:**

Name: <i>Dr. Ghler Saif</i>	Location: <i>Kalar</i>
-----------------------------	------------------------

Machine:

Name: <i>H.A.</i> <input type="checkbox"/>	Type: <i>Alex</i>
Model: <i>motor</i>	Serial No.: <i>BM8B 344A</i>

Inspection:

Lamp shots: <i>2,099, 182</i>	Conductivity: <i>0.6</i>
Rod shots: <i>22, 102, 973</i>	Lenses: <input checked="" type="checkbox"/>
Lamps No.: <i>6</i>	Main shape: <input checked="" type="checkbox"/>
Moveo use: <i>94%</i>	Water leak: <input checked="" type="checkbox"/>
Photod.: External <input checked="" type="checkbox"/> Internal <input checked="" type="checkbox"/>	Electrical & Hydraulic parts: <input checked="" type="checkbox"/>
Results (phtod. & peltier)%: <i>0.7</i>	Power Before replacement: <i>30,6=510</i> After replacement: <i>-</i>
Fiber test: <input checked="" type="checkbox"/>	
Alarms: <i>laser slow.</i>	

Report: *The meaching is stoped case the water pump was stoped which led to burning the hose.*

Actions:

**I Replance the hose and solve the problem the machine working normally.*

Cost:

\$150 ^{dis} → \$100.

Engineer name & signature:

Customer Name & signature

Iraq (Erbil, Duhok, Sulaimanya, Kerkuik, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square