

Date:

2022/3/22

Report Type:

repair maintenance

Customer:

Name: <u>Derma star</u>	Location: <u>Sul</u>
-------------------------	----------------------


Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓ / ✗
<u>D-switch</u>	<u>nd: yag</u>	<u>yag</u>	<u>018201512</u>	<u>0</u>	<u>✓</u>

Report:
The power of the hand piece is low.

Actions:
I change the hand piece.

Price: 7850^{dis} 700

Engineer name & signature:


Customer Name & signature
