

Date:

20-08-2025

Report Type:

Maintenance

Customer:

Name: Dr. Soze Trest	Location: Sul
----------------------	---------------

Machine:

Name: motus Ax	Type: Alexandrite
Model: MA2 A1	Serial No.:

Inspection:

Lamp shots: 1357242	Conductivity: 0.7
Rod shots: 4592003	Lenses: not ok
Lamps No.: 2	Main shape: on
Moveo use: 0%	Water leak: on
Photod.: External - Internal	Electrical & Hydraulic parts: on
Results (phtod. & peltier)%: on	Power
Fiber test: on	
Alarms: No Alarm	After replacement: -

Report:

lens 144 + 141 + 027 was damaged

Actions:

I change the lens 144 + 141 + 027

Cost:

Engineer name & signature:

Customer Name & signature