

Date:

03.09.2015

Report Type:

Administrative

Customer:

Name: Ravison Location: Sul

Machine:

Name: Motor Dr Type: Alexandria
Model: MIRA Serial No.:

Inspection:

Lamp shots:	475,650	Conductivity:	1.1 M
Rod shots:	4721952	Lenses:	on
Lamps No.:	6	Main shape:	on
Moveo use:	0 %	Water leak:	on
Photod.: External -	Internal -	Electrical & Hydraulic parts:	on
Results (phtod. & peltier)%:	-	Power	Before replacement: -
Fiber test:	on	After replacement:	-
Alarms:	laser Flow		

Report:

laser Flow cover

Actions:

I fix a problem in water circuit

Cost:

8100

Engineer name & signature:



Customer Name & signature

