

Date:

Report Type:

26-11-2028

Maintenance

Customer:


Name: <i>Kak Hicaru</i>	Location: <i>Dokan</i>
-------------------------	------------------------

Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓/✗
<i>Zimmer</i>	<i>Air cooling</i>	<i>cry let</i>	<i>ACSU238530</i>	<i>-</i>	<i>X</i>

<p>Report:</p> <p><i>- The control board was damaged</i></p>
<p>Actions:</p> <p><i>- I change the control board</i></p>
<p>Price:</p> <p><i>6600</i></p>

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad, Diyala)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448